Work Orde June-05-12 9:08	er ID 85240 8:10 AM		*852	40*		-				Page 1	
Revision ID:	D412-726-141 Wearplate LH		Accept	*N900	040100	*	Setup	Start Stop	14.	S1* S2*	
Start Date: Required Date: Reference:	05/06/2012 Start Qty: 2.00 19/06/2012 Req'd Qty: 2.00	*2* *2*		Cust Item I Customer:	D:				INI	17	
Approvals:	Process Plan: MLJ QC:	1 1	Tooling: SPC (Y/N):		ate:	J	Run	Start Stop	*NF	₹1* ₹2*	
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool # Plan Code	Accept Qty	Reje Qty			Insp. Stamp	
Draw Nbr	Revision Nbr			··· ·							
N/A	Rev N/A									٨	
*100 *100* DC Document Control	DOCUMENT CONTE Memo Photocopy	OL bluefile and create labels pe	0.00 0.00 er PPP D412-726-142 CHO	6001 JB		2	49	de r	n M5 7	2-6-2	! <i> </i>
110	Pick Kit		0.00								
110 Packaging Packaging	Memo		0.00		S	?	<u></u> .			12/06/20	f
¹²⁰ *12∩*	QC4- 100% Inspect kit	s for completeness	0.00			2				1 12.00) }
QC	Memo		0.00		-	~				M1 10.08 0	1

Quality Control

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	SES		•	
DATE	STEP	PRO	CEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								8
								•
	·					·		
Part No		PAR #:	Fault Cate	jory:	NCR: Yes	No DQA:	Date: _	
	R	esolution:					Date: _	
NCR:		\	WORK ORDI	ER NON-CONFORM	ANCE (NCR)		
DATE	STEP	Description of NC			tion B	Verification	Approval	Approval
DAIL	O I E I	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
	,				i	}		
			!					
								-
		٠.						
		٠ -						
		* -						
		٠						
		5						

140

QC21- Final Inspection - Work Order Release

0.00

140

QC.

Memo

0.00

Quality Control

Insp.

Page 2

Dart Ae	rospace	Ltd								€ je jes
W/O:		· · · · · · · · · · · · · · · · · · ·	W	ORK ORDER CHAN	GES	•				
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
										•
										•
1			· · · · · · · · · · · · · · · · · · ·		.:					
					*			:		
					i					
Part No		PAR #:	Fault Ca	tegory:	NCI	R: Yes N	do DQ	A :	Date:	: :
		esolution:								
NCR:			VORK OR	DER NON-CONFORM	MANCE	(NCR))	, •		
DATE	0750	Description of NC		Corrective Action Se	ection B		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	• •	Sign & Date		ion C	Chief Eng	QC Inspector
-										÷
									<u>.</u>	
		·								

Picklist Print

June-05-12 9:08:14 AM

Work Order ID: 85240

Parent Item: D412-726-141

Parent Item Name: Wearplate LH

85240

D412-726-141

Start Date: 05/06/2012

Required Date: 19/06/2012

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP Rev:A05.05.12New issueKJ/JLM

Comments.													
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN3-5A *AN3=5A* 7 Bolt		Purchased	No	- · · · · · · · · · · · · · · · · · · ·		120	Each	980.0000	**	80	J.	В	
				Location	<u>1</u>	Loc	<u>Qty</u>	Loc Code					
				ST350			980						
					115371		46				_		
					117423		124				_		
					118626		31						
					119355 120187		200 500		287	12018	7		
					120187		79		12×1	2118			
AN960JD10L *AN960.ID	NAS1149D0332J	Purchased	No			120	Each	0.0000	40	80	- -	B	S
Washer D3315-1		Manufactured	No			120	Each	4.0000		$\frac{2}{2}$	1		3.0
P3315-1 Wearplate	•								**		JB		50·
				<u>Location</u>	<u>l</u>	Loc	<u>Qty</u>	Loc Code					
				ST496			4		_	0200			
D3315-3					73225		4		- /-	7322	5		
D8915 3	•	Manufactured	No			120	Each	2.0000	**	2	12	= A	17666
Wearplate											10	\mathcal{B}_{∞}	2/06/2
L				Location	<u>.</u>	Loc	<u>Qty</u>	Loc Code			V		
				ST496			2						
					73227		2			1322	7		

Dart Aerospace Ltd

W/O:		 	W	ORK ORDER CHANGE	ES			· · · · · · · · · · · · · · · · · · ·	
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									4
								ı	•
		-							
,								,	
Part No.	•	PAR #:	Fault Cat	agon!	NCB: Vas	No DO	Δ.	Date:	
r alt HO		esolution:							
NCR:				DER NON-CONFORMA					
NCN:					•	,		<u> </u>	1
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign & Date		cation ion C	Approval Chief Eng	Approval QC inspector
	·					:			
	7					 			
	1	1	l l		1	1		1	1

Picklist Print

June-05-12 9:08:14 AM

Work Order ID: 85240

Parent Item: D412-726-141

Parent Item Name: Wearplate LH

85240 *D412-726-141*

Start Date: 05/06/2012

Required Date: 19/06/2012

Start Qty: 2.00

Required Qty: 2.00



Manufactured No

120

Each 2.0000

Location Loc Qty Loc Code ST496A 2 73229 2



Page 2


June-05-12 9:08:14 AM

Shop Packet Print

Page 2

Dart /	Aeros	pace	Ltd
--------	-------	------	-----

W/O:			V	ORK ORDER CHANG	ES				
DATE	STEP	PROC	EDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									•
1									
<i>į</i>	·								
Part No		PAR #:							<i>,</i>
	R	esolution:	Disposit	ion:	_ QA: N/C (Closed: _		Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section Action Description	on B Sign		ication tion C	Approval Chief Eng	Approval QC Inspector
		GECHOITA	Chief Eng	Chief Eng	Dat			Office Ling	QO mapector
50 .									
	5		:						
-		·						1	
									,
				,					
				•					



• COPYRIGHT © 2005 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision:

В

Date:

06.03.08

WEIGHT AND BALANCE 4.0

There is negligible weight change associated with the installation of the Dart wearplates.

5.0 **PARTS LIST**

Qty -111	Qty -141	Qty -142	Qty -211	Qty -241	Part Number	Description
Х					D412-726-111	WEARPLATE KIT (205/212/412
						Standard Skidtubes)
	Х				D412-726-141	WEARPLATE KIT (205/212/412
i						Standard Skidtubes), LH
		Х			D412-726-142	WEARPLATE KIT (205/212/412
						Standard Skidtubes), RH
			Х		D412-726-211	WEARPLATE KIT (412 Float
						Skidtubes)
				Х	D412-726-241	WEARPLATE KIT (412 Float
						Skidtubes), LH/RH
1	/ 1				D3315-1	WEARPLATE (LH FWD)
1		1			D3315-2	WEARPLATE (RH FWD)
1	L 1_				_D3315 <u>-</u> 3	WEARPLATE (LH CENTER)
1		1			D3315-4	WEARPLATE (RH CENTER)
1	/1-				-D3315-5-	WEARPLATE (LH AFT)
1		1			D3315-6	WEARPLATE (RH AFT)
 .						
			2	1	D3321-1	WEARPLATE (LH FWD, RH MIDDLE)
			2	1	D3321-2	WEARPLATE (RH FWD, LH MIDDLE)
			2	1	D3321-3	WEARPLATE (AFT END)
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
80	/40	40	80	40	AN3-5A	BOLT
80	40_	_40_	_80_	_40_	.AN960JD10L	*WASHER

COPYRIGHT © 2005 BY DART AEROSPACE LTD. ■

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: